	Туре	Hits	Search Text	DBs
1	BRS	18	4,585,284	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	37	4,857,002	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	14	4,952,758	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	8	5,587,685	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
5	BRS	36	5,440,162	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
6	BRS	13	5,155,648	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
7	BRS	11	4,900,951	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
8	BRS	1623	hot same plugging	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	0	hot same plugging same communincation	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
10	BRS	41	hot same plugging same communication	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
11	BRS	323	hot same plug same communication	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	11	hot same plug same communication same connector	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	1711	361/212	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
14	BRS	690	hot same (plug plugging) same connector	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
15	BRS	2	hot same (plug plugging) same connector same sliding same pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
16	BRS	0	hot same (plug plugging) same connector same sliiding adj contact	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	0	hot same (plug plugging) same connector same sliiding same contact	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
1	2002/09/20 11:40			0
2	2002/09/19 16:50			0
3	2002/09/19 16:53			0
4	2002/09/19 16:53			0
5	2002/09/19 16:54			0
6	2002/09/19 16:54			0
7	2002/09/19 17:07			0
8	2002/09/19 17:07			0
9	2002/09/19 17:08			0
10	2002/09/19 17:15			0
11	2002/09/19 17:15			0
12	2002/09/19 17:26			0
13	2002/09/19 17:27			0
14	2002/09/20 09:23			0
15	2002/09/20 09:25			0
16	2002/09/20 09:26			0
17	2002/09/20 10:37			0

	Туре	Hits	Search Text	DBs
18	BRS	87	hot same (plug plugging) same connector same pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	4	hot same (plug plugging) same connector same (ground grounding) adj pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	0	6,374,318 and (ground gounding) adj pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	1	6,374,318 and (ground grounding) adj pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	5	hot same (plug plugging) same communication same connector same pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	0	hot same (plug plugging) same communication same connector same RC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	1	hot same (plug plugging) same connector same RC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	94	hot same (plug plugging swap) same connector same pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
26	BRS	6	hot same (plug plugging swap) same connector same (ground grounding) adj pin	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	15	("3795771" "4727244" "4853555" "4866515" "4896209" "4897714" "5123015" "5203004" "5404567" "5463261" "5473499" "5557541" "5568484" "5586937" "5636347").PN.	USPAT
28	BRS	15	("3795771" "4727244" "4853555" "4866515" "4896209" "4897714" "5123015" "5203004" "5404567" "5463261" "5473499" "5557541" "5568484" "5586937" "5636347").PN.	USPAT
29	BRS	69	5796185.URPN.	USPAT
30	BRS	436	hot same (plug plugging swap) same (filter filtering RC)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
31	BRS	17	hot same (plug plugging swap) same (filter filtering RC) same connector	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
18	2002/09/20 10:26			0
19	2002/09/20 09:47			0
20	2002/09/20 09:47			0
21	2002/09/20 09:47			0
22	2002/09/20 09:57			0
23	2002/09/20 09:57			0
24	2002/09/20 09:57			0
25	2002/09/20 10:26			0
26	2002/09/20 10:37			0
27	2002/09/20 10:29			0
28	2002/09/20 10:30			0
29	2002/09/20 10:35			0
30	2002/09/20 10:38			0
31	2002/09/20 10:52			0

	Туре	Hits	Search Text	DBs
32	BRS	36	5,440,162	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	4	5,440,162 and filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	14	("4821096" "4855647" "4900951" "5155648" "5243232" "5347185" "5392186" "5438213" "5440162" "5504362" "5508548" "5587685" "5744842" "5754074").PN.	USPAT
35	BRS	3311	connector same magnet	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	1	connector same magnet same reed same hot same (plug plugging)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	1	connector same magnet same reed same hot same (plug plugging swap swapping)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
38	BRS	222	connector same magnet same reed	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
39	BRS	14	connector same magnet same reed same communication	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
40	BRS	0	connector same magnet same reed same raid	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
41	BRS	2	connector same magnet same reed same (protect protection)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
42	BRS	0	connector same magnet same reed same transient	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
43	BRS	0	connector same magnet same reed same surge	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
44	BRS	2	connector same magnet same reed same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
45	BRS	2	connector same magnet same reed same bus	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
46	BRS	852	connector same (movable moving) adj (member pin)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
47	BRS	2142	connector same (movable moving) adj (member contact)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
32	2002/09/20 10:53			0
33	2002/09/20 10:53			0
34	2002/09/20 10:55			0
35	2002/09/20 11:40			0
36	2002/09/20 11:43			0
37	2002/09/20 11:43			0
38	2002/09/20 12:00			0
39	2002/09/20 11:44			0
40	2002/09/20 11:52			0
41	2002/09/20 11:54			0
42	2002/09/20 11:54			0
43	2002/09/20 11:54			0
44	2002/09/20 11:55			0
45	2002/09/20 13:32			0
46	2002/09/20 13:34			0
47	2002/09/20 13:34			0

	Туре	Hits	Search Text	DBs
48	BRS	727	connector same (movable moving) adj member	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
49	BRS	217964	connector same (movable moving) adj member same bias biasing	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
50	BRS	44	<pre>connector same (movable moving) adj member same (bias biasing)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
51	BRS	31	connector same (movable moving) adj member same pressing same member	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
52	BRS	9	5,273,448	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
53	BRS	20	connector same (movable moving) adj member same short	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
54	BRS	5	("3525056" "3529264" "3692966" "4429384" "4507627").PN.	USPAT
55	BRS	5	("3525056" "3529264" "3692966" "4429384" "4507627").PN.	USPAT
56	BRS	8	4882554.URPN.	USPAT
57	BRS	2	6,410,869	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
58	BRS	14	("3553395" "3665495" "3697709" "3936782" "4157461" "4295054" "4423336" "4882554" "5233501" "5648745" "5721449" "5898239" "5909154" "5914467").PN.	USPAT
59	BRS	1954	361/58	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors		
48	2002/09/20 13:36			0		
49	2002/09/20 13:36			0		
50	2002/09/20 14:06			0		
51	2002/09/20 14:26			0		
52	2002/09/20 14:24			0		
53	2002/09/20 15:16			0		
54	2002/09/20 14:54			0		
55	2002/09/20 14:54			0		
56	2002/09/20 14:56			0		
57	2002/09/20 15:16			0		
58	2002/09/20 15:17			0		
59	2002/09/20 16:05			0		